



**KITPLANES FOR AFRICA**

**www.saplanes.co.za**

**P.O.Box 326**

**KOMATIPOORT**

**1340**

**South Africa**

**Rick Burrough 082 410032**

**Stefan Coetzee 082 6018970**

**info@saplanes.co.za**

## **SERVICE BULLETIN**

**AIRCRAFT EFFECTED:** Bushbaby

**BULLETIN NUMBER:** SB003

**ORIGINAL ISSUE DATE:** 04-04-02

**REVISION DATE:** 14-11-08

**SUBJECT:** Incorrect FBM-B aileron mixer supplied.

**APPLICABILITY:** SN001 - SN015

**COMPLIANCE:** Mandatory.

**PROBLEM:** A mistake occurred in setting up the FBM-B aileron mixer jig.  
This would cause the ailerons to work the wrong way around.

**SOLUTION:** Contact the factory.  
The correct mixer is available.  
Cut up and discard the old mixer.