



**KITPLANES FOR AFRICA**

**www.saplanes.co.za**

**P.O.Box 326**

**KOMATIPOORT**

**1340**

**South Africa**

**Rick Burrough 082 410032**

**Stefan Coetzee 082 6018970**

**info@saplanes.co.za**

**SERVICE BULLETIN**

**AIRCRAFT EFFECTED:** All models

**BULLETIN NUMBER:** SB014

**ORIGINAL ISSUE DATE:** 01-09-02

**REVISION DATE:** 17-11-08

**SUBJECT:** Axle retaining bolts

**APPLICABILITY:** All aircraft with KFA axles.

**COMPLIANCE:** Mandatory

**Problem:** Some axle retaining bolts were found to be too short and sheared at the thread.

**Solution:** Axle bolts should have the shank protruding from the axle tube by 1mm and be fitted with a washer under the nut.

Remove and inspect the axle retaining bolt at every annual or 100 hour inspection.