



KITPLANES FOR AFRICA

www.saplanes.co.za

P.O.Box 326

KOMATIPOORT

1340

South Africa

Rick Burrough 082 410032

Stefan Coetzee 082 6018970

info@saplanes.co.za

SERVICE BULLETIN

AIRCRAFT EFFECTED: All models

BULLETIN NUMBER: SB015

ORIGINAL ISSUE DATE: 01-09-02

REVISION DATE: 17-11-08

SUBJECT: Horizontal stabilizer attachment tabs broken.

APPLICABILITY: All serial numbers

COMPLIANCE: Mandatory

Problem: Forward horizontal stabilizer tabs were found to be broken.
The tabs had been bent in to meet the vertical fin when bolted up.

Solution: Never bend tabs like this. If the space for mounting is slightly too big, insert washers to take up any free space before bolting up tight.

