



**KITPLANES FOR AFRICA**

**www.saplanes.co.za**

**P.O.Box 326**

**KOMATIPOORT**

**1340**

**South Africa**

**Rick Burrough 082 4100032**

**Stefan Coetzee 082 6018970**

**info@saplanes.co.za**

## **SERVICE BULLETIN**

**AIRCRAFT EFFECTED:** Bushbaby

**BULLETIN NUMBER:** SB021

**ORIGINAL ISSUE DATE:** 23-12-08

**REVISION DATE:** 19-11-08

**SUBJECT:** Back-plates with axles welded onto them

**APPLICABILITY:** All Bushbabies with these fitted

**COMPLIANCE:** Mandatory

**Problem:** Some of the older Bushbabies were fitted with the brake back plate welded onto the axle forming one unit.  
There has been an axle failure where the axle broke at the weld after a hard landing.

**Solution:** It has been decided that the separate axle and back plate is a better design to promote better axle durability.  
Owners who have aircraft fitted with this old design should contact the factory for replacement parts.