



**KITPLANES FOR AFRICA**  
**www.saplanes.co.za**  
**P.O.Box 326**  
**KOMATIPOORT**  
**1340**  
**South Africa**

**Rick Burrough 082 410032      Stefan Coetzee 082 6018970**  
**info@saplanes.co.za**

## **SERVICE BULLETIN**

**AIRCRAFT EFFECTED:** Bushbaby

**BULLETIN NUMBER:** SB001

**ORIGINAL ISSUE DATE:** 04-04-02

**REVISION DATE:** 14-11-08

**SUBJECT:** Tail post insert

**APPLICABILITY:** SN001 - SN015

**COMPLIANCE:** Mandatory. Before next flight

**PROBLEM:** According to our records, some of the earliest Bushbabies were manufactured with the tail-post tube not structurally braced.

**SOLUTION:** Owners of aircraft SN001 - SN015 please contact the factory if this bulletin has not been incorporated.  
A 400mm split tube with one welded end is available for insertion into the original tail-post. Tap the split tube into the tail-post with the welded end up until the mid section of the tail-post is braced.  
The tail-post design was changed after SN015.